





## Dimension and circuit diagrams

### • Dimensions S804



### Circuit diagram



Mount / ganging  
Torque 1.0 Nm max.

Terminal screws  
M3 with saddle clamp  
Torque 0.9 Nm max.

Free position

